

Chimney Sweep

Including smoke evacuation check and issue of NACS Certificate.

Lined stove or open fire £75 (multi discount available, conditions apply)

Stove or open fire with soot door or register plate access £90

Victorian Range Cookers, AGA's, Rayburn's and modern wood burning range cookers £90

Pre-install sweep with CCTV 'look see' Inspection £150

External 'Drone' survey check condition of chimney £125

Nest Removal

Including chimney sweeping, CCTV 'look see' inspection, smoke evacuation check and issue of NACS Certificate. £130 (first hour)

Please Note Additional time may well be required priced at £45 per extra half hour.

Nest removal services are only available from September 1st to February 28th. This is due to the protection of live nests under the Wildlife and Countryside Act 1981.

Internal Chimney CCTV Inspection.

CCTV Inspection, Including sweep, smoke evacuation check and NACS certificate £130 (inc vat)

Please Note this is NOT classed as a full Chimney Survey

Internal Chimney CCTV Survey / HUSP by HETAS Engineer

Chimney CCTV Survey which is a more in-depth camera inspection. Using the latest in pan and tilt camera technology to see fully what is going on in the chimney. This is accompanied by a CCTV survey report which can be utilised by surveyors, estate agents or insurance companies.

Includes external drone survey to examine condition of chimney & termination

Price from £330 (inc VAT)

Lucky wedding Chimney Sweep

Surprise appearance by a lucky chimney sweep, photo opportunities, bespoke gift and of course the luck!

Please do contact us for more information and further details.

Prices starting from £210

Carbon Monoxide alarms

Supply and fitting of Firehawk 7 year CO alarm in accordance to manufacturer's instructions - £35

Servicing add on's whilst attending – Price per chimney/appliance

Replacement stove Door Rope Seal set, prices from £75 must be notified when booking appointment and specialist ropes will incur an additional charge.

Fire cement - Flue connection re-seal £20 (inc vat)

Intense Glass cleaning for Stoves £15 (Inc vat)

Full Stove Servicing £140 (inc vat)

- Replacement Stove Door Rope Seal Set.
- Fire cement - Flue connection re-seal.
- Intense Glass cleaning for Stoves
- Full clean down inside and out.
- Full appliance polish/back to black conditioning.
- Quotation for any replacement parts that are required.

Stove servicing only available January to August

Return visit to fit replacement parts between £40 - £70 (inc vat) dependent on what work is required to fit parts.

Call Out Charge

Un-sweepable chimneys with no sufficient access to carry out the work.

Issue of warning notice for dangerous appliances (not able to sweep).

No one home/forgotten appointment.

£45 including vat